

Attachment 14 –


Aerial Photography

Wasatch Blvd and SR-190


2007 - 2020




Most Recent SL County Imagery



April 17, 2020 Pictometry




December 20, 2019 Pictometry




December 20, 2019 Pictometry




December 20, 2019




October 31, 2019 Pictometry




May 10, 2019 Pictometry



April 8, 2019




November 13, 2017 Pictometry



October 16, 2017 Pictometry



September 26, 2017 Pictometry




November 13, 2016 Pictometry



November 8, 2016 Pictometry



May 27, 2016 Pictometry



March 29, 2015 Pictometry



November 20, 2015 Pictometry




November 26, 2014 Pictometry




March 25, 2014 Pictometry



March 25, 2014 Pictometry




November 27, 2013 Pictometry




November 27, 2013 Pictometry



November 26, 2011 Pictometry



November 2, 2009 Pictometry



October 23, 2007 Pictometry



August 15, 2014



April 2016



June 2019



June 2017

6200 S Wasatch Blvd SR19 @ Wasatch Blvd Millrock Dr CWH

6200 S Wasatch Blvd SR190 @ Wasatch Blvd Millrock Dr CWH



udot.utah.gov 06:10PM 07/08

udot.utah.gov 06:18PM 07/08

Salt Lake City

Salt Lake City

10600 S South Jordan Pkwy SR151 @ 400 W Jordan Gat

10600 S South Jordan Pkwy SR151 @ 400 W Jordan Gat

Incidents +/-

Incidents +/-

Incident accident - SR 36 at MP 63

Direction: SB

Low (less than 5 minutes delays)

Lanes Impacted: 2

E:
D:
C:

There are no active incident(s) to report at this time.



y P
g

Search Google Maps

See travel times, traffic and nearby places

